



PHASE I - DESIGN COORDINATION



PHASE II - DESIGN FOR MANUFACTURING AND ASSEMBLY (DfMA)



PHASE III - PRODUCTION



Major milestone necessary to progress to the next step or phase



By Element5



By client



Jointly

RFI: Request for information
LOD: Level of development